

## Navigation Database Addendum

### **AIRAC 2108 – Issue 4**

**NOTAM A2751/21 effective 23rd May 2021**

**NOTAM A3380/21 effective 7<sup>th</sup> June 2021**

### **UEEE Yakutsk**

---

#### **APCHs for RWY 05R**

#### **Runway 05R/23L**

RWY 05R threshold displacement is **not included** in database.

- RWY 05R threshold should read displaced towards ARP by 1770 meters.
- RWY 05R available for take-off only.
- RWY 23L available for landing only.

RWY 05R threshold coordinates should read **N62-05-40.33 E129-46-36.78**.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 14<sup>th</sup> July 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)