

Navigation Database Addendum

AIRAC 2108 – Issue 25

NOTAM EP F3806/21 effective 30th June 2021

EPLY Leczyca

APCHs RWY 10; Runway 10

RWY 10 landing threshold displacement of 480m is **not included** in database.

Coded APCHs **do not lead** to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 20th August 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com