

## Navigation Database Addendum

### **AIRAC 2108 – Issue 28**

**NOTAM SA A4430/21 effective 20<sup>th</sup> August 2021**

### **SAAR Rosario Islas Malvinas**

---

#### **Runway 20**

RWY 20 THR displacement of **310m not** included in DB.

Vertical guidance should **not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 1<sup>st</sup> September 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)