

## Navigation Database Addendum

### **AIRAC 2109 – Issue 10**

**SUP EY 08/21 effective 26th May 2021**

### **EYSA Siauliai Intl**

---

#### **APCHs RWY 32R; Runway 32R**

RWY 32R threshold displacement of 455m is not included in database.

Vertical Guidance should not be used.  
Coded APCHs do not lead to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 8<sup>th</sup> September 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)