

Navigation Database Addendum

AIRAC 2111 – Issue 1

NOTAM SA A4430/21 effective 20th August 2021

SAAR Rosario Islas Malvinas

Runway 20

RWY 20 THR displacement of **310m not** included in DB.

Vertical guidance should **not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 8th October 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com