

Navigation Database Addendum

AIRAC 2204 – **correction to Issue 9**

SUP FN AIRAC SUP 14/21 effective 24th February 2022

FNLU Luanda / 4th of February

Runway 05

Effective 14th April 2022 until 31st May 2022 -

- RWY 05 landing threshold **temporarily displaced by 1280m**.
- VOR 05 APCH will **not lead** to the displaced landing threshold, vertical guidance **should not** be used.
- Declared distances during this period:

	TORA	TODA	ASDA	LDA
RWY 05	2420 m	2720 m	2420 m	2420 m
RWY 23	2420 m	2420 m	2420 m	2270 m

- Dates may be subject to change. Please consult NOTAMs for latest information.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 6th May 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com