

Navigation Database Addendum

AIRAC 2305 – Issue 5

AMDT VN 05/23 effective 30th April 2023

VNSM Kathmandu FIR

Waypoints LIKHU, BERBO, TEKUT AWYs W41, Y752, J788

Due to late receipt of document, following data is not updated in the NavDB:

Coordinates for WPT **LIKHU** should read **N27-20.2 E086-12.2** (N27-20-14 E086-12-14)

New WPT **BERBO**: **N27-01.4 E086-59.2** (N27-01-23 E086-59-12)

New WPT **TEKUT**: **N28-31.3 E081-07.3** (N28-31-20 E081-07-20)

AWY **W41**: Replace Fix VNPk with POK VOR.

... MANKA – **POK** – PUBOB...

New AWY **Y752**:

KTM - PUBOB - TEKUT (N28-31.3 E081-07.3 / N28-31-20 E081-07-20) - DHI

New AWY **J788**:

KTM - LIKHU - BERBO (N27-01.4 E086-59.2 / N27-01-23 E086-59-12) - BDP

Navdata will be updated effective AIRAC cycle 2306.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 5th May 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com