

Navigation Database Addendum

AIRAC 2402 – Issue 11

SUP S04/24 effective 22nd February 2024

LIBP Pescara

Runway 04/22

From 22 February 2024 runway extension works will take place.
Works are divided into four phases that will be activated by Notam.

Phases 1, 2, 3:

- RWY length 2214 (m)
- Coordinates THR RWY 04 N42 25 26.59 / E014 10 31.81
- THR Elevation RWY 04 45.3ft
- Aerodrome Elevation 45ft
- Take off RWY 22, landing RWY 04 and intersection take off B forbidden.
- ILS not available
- SIDs RWY 22 suspended
- Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

| | TORA (m) | TODA(m) | ASDA(m) | LDA (m) |
|-------------------------|----------|---------|---------|---------------|
| RW04 | 2214 | 2214 | 2214 | not available |
| Intersection take off C | 1625 | 1625 | 1625 | not available |

| | TORA (m) | TODA(m) | ASDA(m) | LDA (m) |
|------|---------------|---------------|---------------|---------|
| RW22 | not available | not available | not available | 2026 |

Phase 4:

ILS/DME RWY 22 operating with new ident IPSC
New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 15th February 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com