

Exclusion List for HWL NavDBs in Cycle 2506

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2506. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
0ID2		May/Flying Joseph Ranch
	APCH	
	R11-M	40
	SID	
	YOYYU1	40
	ZAROD1	40
10X		Uvalde/Ox Ranch
	APCH	
	R17-M	40
	R35-M	40
17XS		Dublin/Quahadi Ranch
	APCH	
	R01	40
	R19	40
640G		Mitchell/Antone Ranch
	APCH	
	R25-M	40
	SID	
	RIFTE1	40
7FL6		Daytona Beach/Spruce Creek
	APCH	
	R06	40
CAH4		Valemount
	SID	
	IRDIM1	40
CAJ9		Fort Ware
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
CBH2		Helmet
	APCH	
	R12	40
	R30	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CBN9			Tsay Keh
	APCH		
		R31	40
CBQ7			Kemess Creek
	APCH		
		R11-Y	40
		R11-Z	40
		R29	40
	SID		
		AVRED1	40
CBW4			Bob Quinn Lake
	APCH		
		R15-Y	40
		R15-Z	40
CBX7			Tumbler Ridge
	APCH		
		R20	40
CCB2			Seabee Mine
	APCH		
		R05	40
		R23	40
CCC2			Winterland
	APCH		
		R32	40
CCE3			Juniper
	APCH		
		R02	40
		R20	40
CCJ3			Boston Brook
	APCH		
		R02	40
		R20	40
CCL3			Christina Lake
	APCH		
		R08	40
		R26	40
CCL6			Chilko Lake/Wilderness Lodge
	APCH		
		R16	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CCR3			Florenceville
	APCH		
		R18-Y	40
		R18-Z	40
		R36-Y	40
		R36-Z	40
CCS4			Chipman
	APCH		
		R09	40
		R27	40
CDA5			St Andrews/Codroy Valley
	APCH		
		R18	40
CDJ4			Clearwater
	APCH		
		R14	40
		R32	40
CDJ5			Strathmore/D.J. Murray
	APCH		
		R16	40
		R34	40
CDP3			Utik Lake/Dennis G Panches Fie
	APCH		
		R09	40
		R27	40
CDT5			Bouctouche
	APCH		
		R09	40
		R27	40
CDU6			Doaktown
	APCH		
		R11	40
		R29	40
CDV2			Downs Gulch
	APCH		
		R05	40
		R23	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CEC4			Hinton/Jasper-Hinton
	APCH		
		R02	40
CEE5			Wabasca
	APCH		
		R07	40
		R25	40
CEG8			North Seal River
	APCH		
		R03	40
		R21	40
CEH3			Ponoka
	APCH		
		R16-Y	40
		R34-Y	40
CEP3			Barrhead
	APCH		
		R07	40
		R25	40
CEU9			Sambaa K e
	APCH		
		R04-Y	40
		R22-Y	40
CFH4			Fox Harbour
	APCH		
		R15	40
		R33	40
CFN6			Primrose
	APCH		
		R14	40
	SID		
		VETPA1	40
CFQ6			Pelly Crossing
	APCH		
		R08	40
		R26	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CFT8			Pelican
	APCH		
		R07	40
		R25	40
CJA3			Morden Rgnl
	APCH		
		R10	40
		R28	40
CJB3			Steinbach
	APCH		
		R15	40
CJK3			Beauval
	APCH		
		R10	40
		R28	40
CJL4			La Loche
	APCH		
		R12	40
		R30	40
CJL8			Kasba Lake
	APCH		
		R02	40
		R20	40
CJP9			Charlot River
	APCH		
		R05-Y	40
		R23	40
CJQ3			Carlyle
	APCH		
		R11	40
		R29	40
CJQ4			Maple Creek
	APCH		
		R06	40
CJW4			Pelican Narrows
	APCH		
		R01	40
		R19	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CJY4			Sandy Bay
		APCH	
		R05	40
		R23	40
CKB2			Patuanak
		APCH	
		R14	40
		R32	40
CKD5			Kipling
		APCH	
		R10	40
CKM8			Opapimiskan Lake
		APCH	
		R12	40
		R30	40
CKZ3			Elk Island
		APCH	
		R06	40
		R24	40
CKZ7			Winkler
		APCH	
		R09	40
		R27	40
CMB2			Meadowbank
		APCH	
		R12-Y	40
		R12-Z	40
		R30-Y	40
		R30-Z	40
CMB7			Maxville/Bourdon Farm
		APCH	
		R16	40
CNL9			Nueltin Lake
		APCH	
		R02	40
		R20	40
CNV8			Edenvale
		APCH	
		R13	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CPB8			Paramount Bistcho/Bistcho
		APCH	
		R09	40
		R27	40
CRL4			Kirby Lake
		APCH	
		R08	40
		R26	40
		SID	
		KIRBY5	40
CRL7			Reindeer Lake
		APCH	
		R07	40
		R25	40
CRW4			Arctic Watch Lodge
		APCH	
		R01	40
		R19	40
		SID	
		ANEGU1	40
CSR8			La Sarre
		APCH	
		R36	40
CSZ4			St-Frederic
		APCH	
		R23	40
CTH7			Riviere-Aux-Saumons
		APCH	
		R10	40
		R28	40
CVB2			Voisey's Bay
		APCH	
		R10	40
		R28	40
CXX2			Wiebenville
		APCH	
		R10	40
		R28	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYAU	Liverpool/South Shore Rgnl		
	APCH		
		R07	40
		R25	40
	SID		
		ODP07	40
CYBG	Bagotville		
	APCH		
		I11-X	40
		I29-X	40
		L11-X	40
		L29-X	40
		R11-X	40
		R29-X	40
CYDL	Dease Lake		
	APCH		
		R03-X	40
		R03-Y	40
		R03-Z	40
		R21-X	40
		R21-Y	40
		R21-Z	40
	SID		
		OMRUN2	40
CYDM	Ross River		
	APCH		
		R09	40
CYFR	Fort Resolution		
	APCH		
		R13-Y	40
		R31-Y	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYKA	Kamloops		
	APCH		
		I09	40
		L27-Y	40
		R09-Y	40
		R09-Z	40
		R27-Y	40
		R27-Z	40
CYLS	Barrie-Orilla/Barrie-Orillia /		
	APCH		
		R10-Y	40
CYLW	Kelowna		
	APCH		
		I16-Y	40
		I16-Z	40
		R16-V	40
		R16-X	40
		R34-Z	40
CYNN	Nejanilini Lake		
	APCH		
		R18	40
		R36	40
CYPZ	Burns Lake		
	APCH		
		R11-Y	40
		R11-Z	40
		R29-Y	40
		R29-Z	40
	SID		
		CYPZ6	40
		VIS11	40
		VIS29	40
CYSH	Smith Falls-Montague/Russ Beac		
	APCH		
		R06	40
		R24	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYTZ			Toronto/B Bishop Toronto City
		APCH	
		R08-W	40
		R08-X	40
		R26-X	40
CYVD			Viriden / R.J.Andrew Fld Reg
		APCH	
		R08	40
		R26	40
CYWY			Wrigley
		APCH	
		R11-Y	40
		R29-Y	40
CYZG			Salluit
		APCH	
		R03-X	40
CYZW			Teslin
		APCH	
		R09-Y	40
		R27-X	40
CZAM			Salmon Arm
		APCH	
		R14	40
		R32	40
CZML			South Cariboo/108 Mile
		APCH	
		R15	40
		R33	40
CZPO			Pinehouse Lake
		APCH	
		R16	40
		R34	40
EBBE			Beauvechain
		SID	
		BE22A	22
		BE22B	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EBBL			Kleine Brogel
		SID	
		BL05A	22
		BL05B	22
		BL05D	22
EBFS			Florennes
		SID	
		FS08A	22
		FS08B	22
		FS08C	22
		FS26A	22
		FS26B	22
		FS26C	22
EGNH			Blackpool
		APCH	
		N10	3
EGNV			Teesside International
		APCH	
		N23	3
EGPO			Stornoway
		APCH	
		L36	3
		N18	3
		N36	3
EGTE			Exeter
		APCH	
		N26	3
EHEH			Eindhoven
		SID	
		EH5	22
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04	1
		J22	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J36	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
ETNG			Geilenkirchen
		SID	
		NG227	22
FA54			Placida/Coral Creek
		APCH	
		R05	40
		R23	40
KASE			Aspen-Pitkin County/Sardy Fld
		APCH	
		L15	40
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19
KDZB			Horseshoe Bay Resort
		APCH	
		R17	40
		R35	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
KEGE			Eagle County Rgnl
		APCH	
		I25	40
		L25-Y	40
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36-Z	19
KHIF			Ogden/Hill AFB
		SID	
		DEVLN1	40
		LGTNG1	40
KJPX			East Hampton Town
		APCH	
		R10-M	40
		R28-M	40
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	41
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KNLC			Lemoore NAS / Reeves Fld
		SID	
		LEM1EO	40
		REV4BU	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
KNQX			Key West NAS (Boca Chica Fld)
		SID	
		NQX6	40
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
		T32RZ	19
KTCM			Tacoma/McChord Fld /Joint Bas
		STAR	
		ARRIE8	40
		WHYTE7	40
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02	19
		T12	19
		T20	19
		T30	19
KWRB			Warner Robins/Robins AFB
		APCH	
		T15-Y	19
		T15-Z	19
		T33-Y	19
		T33-Z	19
LJCE			Cerklje ob Krki
		APCH	
		N09	22
MHTG			Tegucigalpa/Toncontin Intl
		APCH	
		H20	13
MMAN			Monterrey/Del Norte Intl
		APCH	
		D20-4	41

*See Reason Code table on page R1

	Type	Procedure	Reason*
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
PAAD			Deadhorse/Point Thomson Aistr
		APCH	
		R05	40
		R23	40
PABP			Deadhorse/Badami
		APCH	
		R04	40
		R22	40
PACZ			Cape Romanzof LRRS
		APCH	
		R02	40
PADG			Red Dog
		APCH	
		R03	40
		R03-P	40
		SID	
		SICOV1	40
PADQ			Kodiak
		APCH	
		I26-Z	40
		L26-Z	40
PADU			Unalaska
		APCH	
		N13	40
		N31	40
		R13	40
		R31	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
PAGB			Galbraith Lake
	APCH		
		R14	40
	SID		
		ARTIC2	40
PAIM			Utopia Creek/Indian Mountain L
	APCH		
		N25	40
		R25	40
	SID		
		CLYDD4	40
PAJN			Juneau Intl
	APCH		
		R08-T	40
PAKU			Kuparuk/Ugnu-Kuparuk
	APCH		
		I06	40
		I24	40
		L06	40
		L24	40
		R06	40
		R24	40
PAKW			Klawock
	APCH		
		R02-Z	40
PALP			Nuiqsut/Alpine Airstrip
	APCH		
		R04	40
		R22	40
	SID		
		NUQST1	40
PALU			Cape Lisburne LRRS
	APCH		
		R27	40
	SID		
		GRAAY4	40
		LUR8	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
PAPR	Prospect Creek		
	APCH		
		R01-M	40
		R01-Z	40
		R19	40
	SID		
		CYCLE1	40
PASV	Sparrevohn LRRS		
	APCH		
		N35	40
		R35	40
PATC	Tin City LRRS		
	APCH		
		Q35	40
		R35	40
	SID		
		HONPO3	40
		JEKLI3	40
		TNC5	40
PATL	Takotna/Tatalina LRRS		
	APCH		
		R35	40
	SID		
		TLJ4	40
PAVD	Valdez Pioneer Fld		
	SID		
		FJORD1	40
		JOH2	40
RKSM	Seoul Domestic		
	APCH		
		I20-Z	22
		L19-Z	22
		L20-Z	22
TX25	Athens/Lochridge Ranch		
	APCH		
		N17	40
UNSS	Strezhevoy		
	SID		
		BUNA1Z	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55