

Exclusion List for HWL NavDBs in Cycle 2507

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2507. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
01D2		May/Flying Joseph Ranch
	APCH	
	R11-M	40
	SID	
	YOYYU1	40
	ZAROD1	40
10X		Uvalde/Ox Ranch
	APCH	
	R17-M	40
	R35-M	40
17XS		Dublin/Quahadi Ranch
	APCH	
	R01	40
	R19	40
640G		Mitchell/Antone Ranch
	APCH	
	R25-M	40
	SID	
	RIFTE1	40
7FL6		Daytona Beach/Spruce Creek
	APCH	
	R06	40
CAH4		Valemount
	SID	
	IRDIM1	40
CAJ9		Fort Ware
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
CBH2		Helmet
	APCH	
	R12	40
	R30	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CBN9			Tsay Keh
	APCH	R31	40
CBQ7			Kemess Creek
	APCH	R11-Y	40
		R11-Z	40
		R29	40
	SID	AVRED1	40
CBW4			Bob Quinn Lake
	APCH	R15-Y	40
		R15-Z	40
CBX7			Tumbler Ridge
	APCH	R20	40
CCB2			Seabee Mine
	APCH	R05	40
		R23	40
CCC2			Winterland
	APCH	R32	40
CCE3			Juniper
	APCH	R02	40
		R20	40
CCJ3			Boston Brook
	APCH	R02	40
		R20	40
CCL3			Christina Lake
	APCH	R08	40
		R26	40
CCL6			Chilko Lake/Wilderness Lodge
	APCH	R16	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CCR3			Florenceville
		APCH	
		R18-Y	40
		R18-Z	40
		R36-Y	40
		R36-Z	40
CCS4			Chipman
		APCH	
		R09	40
		R27	40
CDA5			St Andrews/Codroy Valley
		APCH	
		R18	40
CDJ4			Clearwater
		APCH	
		R14	40
		R32	40
CDJ5			Strathmore/D.J. Murray
		APCH	
		R16	40
		R34	40
CDP3			Utik Lake/Dennis G Panches Fie
		APCH	
		R09	40
		R27	40
CDT5			Bouctouche
		APCH	
		R09	40
		R27	40
CDU6			Doaktown
		APCH	
		R11	40
		R29	40
CDV2			Downs Gulch
		APCH	
		R05	40
		R23	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CEC4			Hinton/Jasper-Hinton
		APCH	
		R02	40
CEE5			Wabasca
		APCH	
		R07	40
		R25	40
CEG8			North Seal River
		APCH	
		R03	40
		R21	40
CEH3			Ponoka
		APCH	
		R16-Y	40
		R34-Y	40
CEP3			Barrhead
		APCH	
		R07	40
		R25	40
CEU9			Sambaa K e
		APCH	
		R04-Y	40
		R22-Y	40
CFH4			Fox Harbour
		APCH	
		R15	40
		R33	40
CFN6			Primrose
		APCH	
		R14	40
		SID	
		VETPA1	40
CFQ6			Pelly Crossing
		APCH	
		R08	40
		R26	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CFT8			Pelican
		APCH	
		R07	40
		R25	40
CJA3			Morden Rgnl
		APCH	
		R10	40
		R28	40
CJB3			Steinbach
		APCH	
		R15	40
CJK3			Beauval
		APCH	
		R10	40
		R28	40
CJL4			La Loche
		APCH	
		R12	40
		R30	40
CJL8			Kasba Lake
		APCH	
		R02	40
		R20	40
CJP9			Charlot River
		APCH	
		R05-Y	40
		R23	40
CJQ3			Carlyle
		APCH	
		R11	40
		R29	40
CJQ4			Maple Creek
		APCH	
		R06	40
CJW4			Pelican Narrows
		APCH	
		R01	40
		R19	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CJY4			Sandy Bay
		APCH	
		R05	40
		R23	40
CKB2			Patuanak
		APCH	
		R14	40
		R32	40
CKD5			Kipling
		APCH	
		R10	40
CKM8			Opapimiskan Lake
		APCH	
		R12	40
		R30	40
CKZ3			Elk Island
		APCH	
		R06	40
		R24	40
CKZ7			Winkler
		APCH	
		R09	40
		R27	40
CMB2			Meadowbank
		APCH	
		R12-Y	40
		R12-Z	40
		R30-Y	40
		R30-Z	40
CMB7			Maxville/Bourdon Farm
		APCH	
		R16	40
CNL9			Nueltin Lake
		APCH	
		R02	40
		R20	40
CNV8			Edenvale
		APCH	
		R13	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CPB8		Paramount Bistcho/Bistcho
	APCH	
	R09	40
	R27	40
CRL4		Kirby Lake
	APCH	
	R08	40
	R26	40
	SID	
	KIRBY5	40
CRL7		Reindeer Lake
	APCH	
	R07	40
	R25	40
CRW4		Arctic Watch Lodge
	APCH	
	R01	40
	R19	40
	SID	
	ANEGU1	40
CSR8		La Sarre
	APCH	
	R36	40
CSZ4		St-Frederic
	APCH	
	R23	40
CTH7		Riviere-Aux-Saumons
	APCH	
	R10	40
	R28	40
CVB2		Voisey's Bay
	APCH	
	R10	40
	R28	40
CXX2		Wiebenville
	APCH	
	R10	40
	R28	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CYAU		Liverpool/South Shore Rgnl
	APCH	
	R07	40
	R25	40
	SID	
	ODP07	40
	ODP25	40
CYBG		Bagotville
	APCH	
	I11-X	40
	I29-X	40
	L11-X	40
	L29-X	40
	R11-X	40
	R29-X	40
CYDL		Dease Lake
	APCH	
	R03-X	40
	R03-Y	40
	R03-Z	40
	R21-X	40
	R21-Y	40
	R21-Z	40
	SID	
	OMRUN2	40
	TIBID1	40
CYDM		Ross River
	APCH	
	R09	40
CYFR		Fort Resolution
	APCH	
	R13-Y	40
	R31-Y	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CYKA		Kamloops
	APCH	
	I09	40
	L27-Y	40
	R09-Y	40
	R09-Z	40
	R27-Y	40
	R27-Z	40
CYLS		Barrie-Orilla/Barrie-Orillia /
	APCH	
	R10-Y	40
CYLW		Kelowna
	APCH	
	I16-Y	40
	I16-Z	40
	R16-V	40
	R16-X	40
	R34-Z	40
CYNN		Nejanilini Lake
	APCH	
	R18	40
	R36	40
CYPZ		Burns Lake
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
	SID	
	CYPZ6	40
	VIS11	40
	VIS29	40
CYSH		Smith Falls-Montague/Russ Beac
	APCH	
	R06	40
	R24	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYTZ			Toronto/B Bishop Toronto City
		APCH	
		R08-W	40
		R08-X	40
		R26-X	40
CYVD			Virден / R.J.Andrew Fld Reg
		APCH	
		R08	40
		R26	40
CYWY			Wrigley
		APCH	
		R11-Y	40
		R29-Y	40
CYZG			Salluit
		APCH	
		R03-X	40
CYZW			Teslin
		APCH	
		R09-Y	40
		R27-X	40
CZAM			Salmon Arm
		APCH	
		R14	40
		R32	40
CZML			South Cariboo/108 Mile
		APCH	
		R15	40
		R33	40
CZPO			Pinehouse Lake
		APCH	
		R16	40
		R34	40
EBBE			Beauvechain
		SID	
		BE22A	22
		BE22B	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EBBL			Kleine Brogel
		SID	
		BL05A	22
		BL05B	22
		BL05D	22
EBFS			Florennes
		SID	
		FS08A	22
		FS08B	22
		FS08C	22
		FS26A	22
		FS26B	22
		FS26C	22
EGNH			Blackpool
		APCH	
		N10	3
EGNV			Teesside International
		APCH	
		N23	3
EGPO			Stornoway
		APCH	
		L36	3
		N18	3
		N36	3
EGTE			Exeter
		APCH	
		N26	3
EHEH			Eindhoven
		SID	
		EH5	22
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1

*See Reason Code table on page R1

Type	Procedure	Reason*
ENBS		Batsfjord
	APCH	
	J03	1
	J21	1
ENBV		Berlevag
	APCH	
	J06	1
	J24	1
ENHF		Hammerfest
	APCH	
	J04	1
	J22	1
ENHK		Hasvik
	APCH	
	J11	1
	J29	1
ENLK		Leknes
	APCH	
	J20	1
ENMH		Mehamn
	APCH	
	J17	1
	J35	1
ENNM		Namsos
	APCH	
	J07	1
	J25	1
ENRM		Rorvik/Ryum
	APCH	
	J04	1
	J22	1
ENRS		Rost
	APCH	
	J02	1
	J20	1
ENSH		Svolvaer/Helle
	APCH	
	J36	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
ETNG			Geilenkirchen
		SID	
		NG227	22
FA54			Placida/Coral Creek
		APCH	
		R05	40
		R23	40
KASE			Aspen-Pitkin County/Sardy Fld
		APCH	
		L15	40
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19
KDZB			Horseshoe Bay Resort
		APCH	
		R17	40
		R35	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
KEGE			Eagle County Rgnl
		APCH	
		I25	40
		L25-Y	40
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36-Z	19
KHIF			Ogden/Hill AFB
		SID	
		DEVLN1	40
		LGTNG1	40
KJPX			East Hampton Town
		APCH	
		R10-M	40
		R28-M	40
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	41
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KNLC			Lemoore NAS / Reeves Fld
		SID	
		LEM1EO	40
		REV4BU	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
KNQX			Key West NAS (Boca Chica Fld)
		SID	
		NQX6	40
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
	T32RZ	19	
KTCM			Tacoma/McChord Fld /Joint Bas
		STAR	
		ARRIE8	40
		WHYTE7	40
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02	19
		T12	19
		T20	19
	T30	19	
KWRB			Warner Robins/Robins AFB
		APCH	
		T15-Y	19
		T15-Z	19
		T33-Y	19
	T33-Z	19	
LJCE			Cerklje ob Krki
		APCH	
		N09	22
MHTG			Tegucigalpa/Toncontin Intl
		APCH	
		H20	13
MMAN			Monterrey/Del Norte Intl
		APCH	
		D20-4	41

*See Reason Code table on page R1

	Type	Procedure	Reason*
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
PAAD			Deadhorse/Point Thomson Aistr
		APCH	
		R05	40
		R23	40
PABP			Deadhorse/Badami
		APCH	
		R04	40
		R22	40
PACZ			Cape Romanzof LRRS
		APCH	
		R02	40
PADG			Red Dog
		APCH	
		R03	40
		R03-P	40
	SID		
		SICOV1	40
PADQ			Kodiak
		APCH	
		I26-Z	40
		L26-Z	40
PADU			Unalaska
		APCH	
		N13	40
		N31	40
		R13	40
		R31	40

*See Reason Code table on page R1

Type	Procedure	Reason*
PAGB		Galbraith Lake
	APCH	
	R14	40
	SID	
	ARTIC2	40
PAIM		Utopia Creek/Indian Mountain L
	APCH	
	N25	40
	R25	40
	SID	
	CLYDD4	40
PAJN		Juneau Intl
	APCH	
	R08-T	40
PAKU		Kuparuk/Ugnu-Kuparuk
	APCH	
	I06	40
	I24	40
	L06	40
	L24	40
	R06	40
R24	40	
PAKW		Klawock
	APCH	
	R02-Z	40
PALP		Nuiqsut/Alpine Airstrip
	APCH	
	R04	40
	R22	40
	SID	
	NUQST1	40
PALU		Cape Lisburne LRRS
	APCH	
	R27	40
	SID	
	GRAAY4	40
	LUR8	40

*See Reason Code table on page R1

Type	Procedure	Reason*
PAPR		Prospect Creek
	APCH	
	R01-M	40
	R01-Z	40
	R19	40
SID		
	CYCLE1	40
PASV		Sparrevohn LRRS
	APCH	
	N35	40
	R35	40
PATC		Tin City LRRS
	APCH	
	Q35	40
	R35	40
	SID	
	HONPO3	40
	JEKLI3	40
TNC5	40	
PATL		Takotna/Tatalina LRRS
	APCH	
	R35	40
	SID	
TLJ4	40	
PAVD		Valdez Pioneer Fld
	SID	
	FJORD1	40
	JOH2	40
RKSM		Seoul Domestic
	APCH	
	I20-Z	22
	L19-Z	22
	L20-Z	22
TX25		Athens/Lochridge Ranch
	APCH	
	N17	40
UNSS		Strezhevoy
	SID	
	BUNA1Z	22

*See Reason Code table on page R1

Type	Procedure	Reason*
VTBK		Nakhon Pathom/Kamphaeng Saen
	APCH	
	V21	2

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55