

## Procedures removed from ARINC output Cycle 2509

|             | Type | Procedure | Transition | Reason                                                                                          |
|-------------|------|-----------|------------|-------------------------------------------------------------------------------------------------|
| <b>AYKV</b> |      |           |            | Kavieng                                                                                         |
|             |      | APCH      |            |                                                                                                 |
|             |      | R30       | YKVED      | Notam AY A1069/22 THR RWY 30 coordinates changed                                                |
|             |      | R30       | YKVEE      | Notam AY A1069/22 THR RWY 30 coordinates changed                                                |
|             |      | R30       | YKVEG      | Notam AY A1069/22 THR RWY 30 coordinates changed                                                |
|             |      | R30       |            | Notam AY A1069/22 THR RWY 30 coordinates changed                                                |
| <b>DAUB</b> |      |           |            | Biskra / Mohamed Khider                                                                         |
|             |      | APCH      |            |                                                                                                 |
|             |      | I31       | BIS        | RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly. |
|             |      | I31       |            | RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly. |
| <b>DNMN</b> |      |           |            | Minna                                                                                           |
|             |      | APCH      |            |                                                                                                 |
|             |      | I05       | MNA        | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | I05       |            | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | L05       | MNA        | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | L05       |            | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | V05       | MNA        | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | V05       |            | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | V23       | MNA        | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |
|             |      | V23       |            | MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.            |

|             | Type | Procedure | Transition | Reason                                                                                         |
|-------------|------|-----------|------------|------------------------------------------------------------------------------------------------|
| <b>EGVN</b> |      |           |            | Brize Norton AB                                                                                |
|             | SID  |           |            |                                                                                                |
|             |      | ALPHA     | RW07       | Different Endfixes not possible                                                                |
|             |      | ALPHA     | RW25       | Different Endfixes not possible                                                                |
|             |      | BRAVO     | RW07       | Different Endfixes not possible                                                                |
|             |      | BRAVO     | RW25       | Different Endfixes not possible                                                                |
| <b>FMMS</b> |      |           |            | Sainte Marie                                                                                   |
|             | APCH |           |            |                                                                                                |
|             |      | N01       | SM         | ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD |
|             |      | N01       |            | ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD |
|             |      | N19       | SM         | ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD |
|             |      | N19       |            | ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD |
| <b>FNLU</b> |      |           |            | Luanda / 4th of February                                                                       |
|             | APCH |           |            |                                                                                                |
|             |      | I23       | ONTAR      | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |
|             |      | I23       | R080L      | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |
|             |      | I23       |            | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |
|             |      | L23       | ONTAR      | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |
|             |      | L23       | R080L      | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |
|             |      | L23       |            | FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.  |

|             | Type | Procedure | Transition | Reason                                                                         |
|-------------|------|-----------|------------|--------------------------------------------------------------------------------|
| <b>FZMA</b> |      |           |            | Bukavu / Kavumu                                                                |
|             |      | APCH      |            |                                                                                |
|             |      | R35       | DOPEM      | Incorrect Source: AIRAC AIP SUP S3006/06                                       |
|             |      | R35       | OSLON      | Incorrect Source: AIRAC AIP SUP S3006/06                                       |
|             |      | R35       |            | Incorrect Source: AIRAC AIP SUP S3006/06                                       |
| <b>GLRB</b> |      |           |            | Monrovia / Roberts Intl                                                        |
|             |      | APCH      |            |                                                                                |
|             |      | I04       | ROB        | GL AIRAC SUP 09/24 new ILS approach established, OLD one not removed OFFset 5° |
|             |      | I04       |            | GL AIRAC SUP 09/24 new ILS approach established, OLD one not removed OFFset 5° |
|             |      | L04       | ROB        | GL AIRAC SUP 09/24 new ILS approach established, OLD one not removed OFFset 5° |
|             |      | L04       |            | GL AIRAC SUP 09/24 new ILS approach established, OLD one not removed OFFset 5° |
| <b>HKLK</b> |      |           |            | Lokichoggio                                                                    |
|             |      | APCH      |            |                                                                                |
|             |      | H27       | EPSUT      | HK Notam B0002/21                                                              |
|             |      | H27       |            | HK Notam B0002/21                                                              |
| <b>KCLR</b> |      |           |            | Calipatria / Cliff Hatfield Mem, CA                                            |
|             |      | APCH      |            |                                                                                |
|             |      | R08       | BOREN      |                                                                                |
|             |      | R08       |            |                                                                                |
| <b>KLCK</b> |      |           |            | Columbus / Rickenbacker Intl, OH                                               |
|             |      | APCH      |            |                                                                                |
|             |      | R05L      | GAILL      |                                                                                |
|             |      | R05L      | HIGID      |                                                                                |
|             |      | R05L      | TARTO      |                                                                                |
|             |      | R05L      |            | not trusted due to calc. angle of 3.16°                                        |

|             | Type                                      | Procedure | Transition | Reason                                                                                               |
|-------------|-------------------------------------------|-----------|------------|------------------------------------------------------------------------------------------------------|
| <b>OAKB</b> | Kabul Intl                                |           |            |                                                                                                      |
|             | SID                                       |           |            |                                                                                                      |
|             |                                           | TAPIS2    | RW11       | RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)             |
|             | APCH                                      |           |            |                                                                                                      |
|             |                                           | R29       |            | RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)             |
| <b>OJMS</b> | Shaheed Muwaffaq / Muwaffaq Salti Airbase |           |            |                                                                                                      |
|             | APCH                                      |           |            |                                                                                                      |
|             |                                           | I26       | JULEZ      | The RWY has been shortened by DoD-FLIP, WEF 10-JUL-2025 but the procedures have not been revised yet |
|             |                                           | I26       |            | The RWY has been shortened by DoD-FLIP, WEF 10-JUL-2025 but the procedures have not been revised yet |
| <b>RJCC</b> | Sapporo / New Chitose                     |           |            |                                                                                                      |
|             | APCH                                      |           |            |                                                                                                      |
|             |                                           | I19RW     |            | SUP 128/25 eff 07Aug25 till 27Nov25 offset LOC antenna.                                              |
|             |                                           | I19RY     |            | SUP 128/25 eff 07Aug25 till 27Nov25 offset LOC antenna.                                              |
|             |                                           | L19RW     |            | SUP 128/25 eff 07Aug25 till 27Nov25 offset LOC antenna.                                              |
|             |                                           | L19RY     |            | SUP 128/25 eff 07Aug25 till 27Nov25 offset LOC antenna.                                              |
| <b>RJEC</b> | Asahikawa                                 |           |            |                                                                                                      |
|             | APCH                                      |           |            |                                                                                                      |
|             |                                           | I34-X     | AWE        | ILS transmitters "IAW" are replaced by a temporary installation due to WIP as per SUP 81/25          |
|             |                                           | I34-X     |            | ILS transmitters "IAW" are replaced by a temporary installation due to WIP as per SUP 81/25          |
|             |                                           | L34-X     | AWE        | ILS transmitters "IAW" are replaced by a temporary installation due to WIP as per SUP 81/25          |
|             |                                           | L34-X     |            | ILS transmitters "IAW" are replaced by a temporary installation due to WIP as per SUP 81/25          |

|             | Type | Procedure | Transition | Reason                                |
|-------------|------|-----------|------------|---------------------------------------|
| <b>UERP</b> |      |           |            | Poliarny                              |
|             | SID  |           |            |                                       |
|             |      | ABNI1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | BAGO1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | BALU1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | DEDO1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | FADR1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | GILA1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | INDI1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | NERD1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | OGON1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | PELI1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | PIRO1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | RUSE1F    | RW36       | NTM UE C3683/25 (proc not to be used) |
|             |      | SUGI1F    | RW36       | NTM UE C3683/25 (proc not to be used) |

| Type | Procedure | Transition | Reason                                |
|------|-----------|------------|---------------------------------------|
| STAR |           |            |                                       |
|      | ABNI1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | ABNI1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | BAGO1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | BAGO1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | BALU1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | BALU1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | DEDO1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | DEDO1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | FADR1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | FADR1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | GILA1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | GILA1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | INDI1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | INDI1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | NERD1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | NERD1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | OGON1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | OGON1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | PELI1L    | RW18       | NTM UE C3683/25 (proc not to be used) |

| Type | Procedure | Transition | Reason                                |
|------|-----------|------------|---------------------------------------|
|      | PELI1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | PIRO1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | PIRO1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | RUSE1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | RUSE1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
|      | SUGI1L    | RW18       | NTM UE C3683/25 (proc not to be used) |
|      | SUGI1L    | RW36       | NTM UE C3683/25 (proc not to be used) |
| APCH |           |            |                                       |
|      | J18       | RP003      | NTM UE C3298/24                       |
|      | J18       | RP004      | NTM UE C3298/24                       |
|      | J18       |            | NTM UE C3298/24                       |
|      | V18       | PLR        | NTM UE C3683/25 (proc not to be used) |
|      | V18       |            | NTM UE C3683/25 (proc not to be used) |
|      | V36       | PLR        | NTM UE C3683/25 (proc not to be used) |
|      | V36       |            | NTM UE C3683/25 (proc not to be used) |

| Type        | Procedure | Transition | Reason                                                                                            |
|-------------|-----------|------------|---------------------------------------------------------------------------------------------------|
| <b>UIBB</b> |           |            | Bratsk                                                                                            |
|             | APCH      |            |                                                                                                   |
|             | I30       |            | NTM UI A2610/25 (-30OCT25 2359), landing threshold RWY 30 tempo displaced by 360 meters. ILS U/S. |
|             | J30       | BB011      | NTM UI A2610/25 (-30OCT25 2359), landing threshold RWY 30 tempo displaced by 360 meters. ILS U/S. |
|             | J30       | BB012      | NTM UI A2610/25 (-30OCT25 2359), landing threshold RWY 30 tempo displaced by 360 meters. ILS U/S. |
|             | J30       | BB013      | NTM UI A2610/25 (-30OCT25 2359), landing threshold RWY 30 tempo displaced by 360 meters. ILS U/S. |
|             | J30       |            | NTM UI A2610/25 (-30OCT25 2359), landing threshold RWY 30 tempo displaced by 360 meters. ILS U/S. |
| <b>UTAK</b> |           |            | Turkmenbashi                                                                                      |
|             | APCH      |            |                                                                                                   |
|             | N34R      |            | NTM UT O0023/24 (no minma for new situation based on this NTM) pending new charts                 |
| <b>UUOO</b> |           |            | Voronezh / Chertovitskoye                                                                         |
|             | APCH      |            |                                                                                                   |
|             | J30       | OO303      | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | J30       |            | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-U     | A          | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-U     | AHI        | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-U     |            | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-V     | A          | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-V     | AHI        | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | N30-V     |            | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | R30       | OO303      | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |
|             | R30       |            | U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.                              |

|             | Type | Procedure | Transition | Reason      |
|-------------|------|-----------|------------|-------------|
| <b>YPTN</b> |      |           |            | Tindal, NT  |
|             | APCH |           |            |             |
|             |      | I14-Z     | TN         | SUP H 27/22 |
|             |      | I14-Z     |            | SUP H 27/22 |