

Exclusion List for HWL NavDBs in Cycle 2513

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2513. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
0ID2		May/Flying Joseph Ranch
	APCH	
	R11-M	40
	SID	
	YOYYU1	40
	ZAROD1	40
10X		Uvalde/Ox Ranch
	APCH	
	R17-M	40
	R35-M	40
17XS		Dublin/Quahadi Ranch
	APCH	
	R01	40
	R19	40
640G		Mitchell/Antone Ranch
	APCH	
	R25-M	40
	SID	
	RIFTE1	40
7FL6		Daytona Beach/Spruce Creek
	APCH	
	R06	40
CAJ9		Fort Ware
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
CAM2		Misaw Lake
	APCH	
	R01	40
	R19	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CBH2			Helmet
	APCH		
		R12	40
		R30	40
CBN9			Tsay Keh
	APCH		
		R31	40
CBQ7			Kemess Creek
	APCH		
		R11-Y	40
		R11-Z	40
		R29	40
	SID		
		AVRED1	40
CBW4			Bob Quinn Lake
	APCH		
		R15-Y	40
		R15-Z	40
CBX7			Tumbler Ridge
	APCH		
		R20	40
	SID		
		KISKK6	40
CCB2			Seabee Mine
	APCH		
		R05	40
		R23	40
CCE3			Juniper
	APCH		
		R02	40
		R20	40
CCJ3			Boston Brook
	APCH		
		R02	40
		R20	40
CCL3			Christina Lake
	APCH		
		R08	40
		R26	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CCL6			Chilko Lake/Wilderness Lodge
	APCH		
		R16	40
CCR3			Florenceville
	APCH		
		R18-Y	40
		R18-Z	40
		R36-Y	40
		R36-Z	40
CCS4			Chipman
	APCH		
		R09	40
		R27	40
CDA5			St Andrews/Codroy Valley
	SID		
		ODP18	40
		ODP36	40
CDJ4			Clearwater
	APCH		
		R14	40
		R32	40
CDJ5			Strathmore/D.J. Murray
	APCH		
		R16	40
		R34	40
CDP3			Utik Lake/Dennis G Panches Fie
	APCH		
		R09	40
		R27	40
CDT5			Bouctouche
	APCH		
		R09	40
		R27	40
CDU6			Doaktown
	APCH		
		R11	40
		R29	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CDV2			Downs Gulch
		APCH	
		R05	40
		R23	40
CEC4			Hinton/Jasper-Hinton
		APCH	
		R02	40
CEE5			Wabasca
		APCH	
		R07	40
		R25	40
CEG8			North Seal River
		APCH	
		R03	40
		R21	40
CEH3			Ponoka
		APCH	
		R16-Y	40
		R34-Y	40
CEP3			Barrhead
		APCH	
		R07	40
		R25	40
CEU9			Sambaa K e
		APCH	
		R04-Y	40
		R22-Y	40
CFH4			Fox Harbour
		APCH	
		R15	40
		R33	40
CFN6			Primrose
		APCH	
		R14	40
		SID	
		VETPA1	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CFQ6			Pelly Crossing
	APCH		
		R08	40
		R26	40
CFT8			Pelican
	APCH		
		R07	40
		R25	40
CHB3			Hope Bay
	APCH		
		R01	40
		R19	40
CJA3			Morden Rgnl
	APCH		
		R10	40
		R28	40
CJB3			Steinbach
	APCH		
		R15	40
CJK3			Beauval
	APCH		
		R10	40
		R28	40
CJL4			La Loche
	APCH		
		R12	40
		R30	40
CJL8			Kasba Lake
	APCH		
		R02	40
		R20	40
CJP9			Charlot River
	APCH		
		R05-Y	40
		R23	40
CJQ3			Carlyle
	APCH		
		R11	40
		R29	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CJQ4			Maple Creek
		APCH	
		R06	40
CJW4			Pelican Narrows
		APCH	
		R01	40
		R19	40
CJY4			Sandy Bay
		APCH	
		R05	40
		R23	40
CKB2			Patuanak
		APCH	
		R14	40
		R32	40
CKD5			Kipling
		APCH	
		R10	40
CKM8			Opapimiskan Lake
		APCH	
		R12	40
		R30	40
CKZ3			Elk Island
		APCH	
		R06	40
		R24	40
CKZ7			Winkler
		APCH	
		R09	40
		R27	40
CMB2			Meadowbank
		APCH	
		R12-Y	40
		R12-Z	40
		R30-Y	40
		R30-Z	40
CMB7			Maxville/Bourdon Farm
		APCH	
		R16	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CNL9			Nueltin Lake
	APCH		
		R02	40
		R20	40
CNV8			Edenvale
	APCH		
		R13	40
CRL4			Kirby Lake
	APCH		
		R08	40
		R26	40
	SID		
		KIRBY5	40
CRW4			Arctic Watch Lodge
	APCH		
		R01	40
		R19	40
	SID		
		ANEGU1	40
CSR3			Victoriaville Andre-Fortin
	APCH		
		R24	40
CSR8			La Sarre
	APCH		
		R36	40
CSZ4			St-Frederic
	APCH		
		R23	40
CTH7			Riviere-Aux-Saumons
	APCH		
		R10	40
		R28	40
CVB2			Voisey's Bay
	APCH		
		R10	40
		R28	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYAU	Liverpool/South Shore Rgnl		
	APCH		
		R07	40
		R25	40
	SID		
		ODP07	40
		ODP25	40
CYBG	Bagotville		
	APCH		
		I11-X	40
		I29-X	40
		L11-X	40
		L29-X	40
		R11-X	40
		R29-X	40
CY CZ	Fairmont Hot Springs		
	SID		
		TEVED1	40
CYDL	Dease Lake		
	APCH		
		R03-X	40
		R03-Y	40
		R03-Z	40
		R21-X	40
		R21-Y	40
		R21-Z	40
	SID		
		OMRUN2	40
		TIBID1	40
CYDM	Ross River		
	APCH		
		R09	40
CYFR	Fort Resolution		
	APCH		
		R13-Y	40
		R31-Y	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYIB			Atikokan Muni
		APCH	
		R04	40
		R22	40
CYKA			Kamloops
		APCH	
		I09	40
		L27-Y	40
		R09-Y	40
		R09-Z	40
		R27-Y	40
		R27-Z	40
CYLS			Barrie-Orilla/Barrie-Orillia /
		APCH	
		R10	40
CYLW			Kelowna
		APCH	
		I16-Y	40
		I16-Z	40
		R16-V	40
		R16-X	40
		R34-Z	40
CYMW			Maniwaki
		APCH	
		R21	40
CYNN			Nejanilini Lake
		APCH	
		R18	40
		R36	40
CYPZ			Burns Lake
		APCH	
		R11-Y	40
		R11-Z	40
		R29-Y	40
		R29-Z	40
		SID	
		CYPZ6	40
		ODPV	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYSH			Smith Falls-Montague/Russ Beac
		APCH	
		R06	40
		R24	40
CYTB			Tillsonburg
		APCH	
		R26	40
CYTZ			Toronto/B Bishop Toronto City
		APCH	
		R08-W	40
		R08-X	40
		R26-X	40
CYZG			Salluit
		APCH	
		R03-X	40
CYZW			Teslin
		APCH	
		R09-Y	40
		R27-X	40
CZAM			Salmon Arm
		APCH	
		R14	40
		R32	40
CZML			South Cariboo/108 Mile
		APCH	
		R15	40
		R33	40
CZPO			Pinehouse Lake
		APCH	
		R16	40
		R34	40
DATM			Bordj Mokhtar
		APCH	
		V26	2
EBBE			Beauvechain
		SID	
		BE22A	22
		BE22B	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EBFS			Florennes
		SID	
		FS08A	22
		FS08B	22
		FS08C	22
		FS08D	22
		FS08E	22
		FS26A	22
		FS26B	22
		FS26C	22
		FS26D	22
		FS26E	22
EGNH			Blackpool
		APCH	
		N10	3
EGNV			Teesside International
		APCH	
		N23	3
EGPO			Stornoway
		APCH	
		L36	3
		N18	3
		N36	3
EGTE			Exeter
		APCH	
		N26	3
EHEH			Eindhoven
		SID	
		EH5	22
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04-Z	1
		J22-Z	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J36	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
ETNG			Geilenkirchen
		SID	
		NG227	22
FA54			Placida/Coral Creek
		APCH	
		R05	40
		R23	40
KASE			Aspen-Pitkin County/Sardy Fld
		APCH	
		L15	40
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19
KDZB			Horseshoe Bay Resort
		APCH	
		R17	40
		R35	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
KEGE			Eagle County Rgnl
		APCH	
		I25	40
		L25-Y	40
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36	19
KHIF			Ogden/Hill AFB
		SID	
		DEVLN1	40
		LGTNG1	40
KJPX			East Hampton Town
		APCH	
		R10-M	40
		R28-M	40
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01-Y	19
		T01-Z	19
		T19-Y	19
		T19-Z	19
KMTN			Baltimore/Martin State
		APCH	
		T15	41
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KNLC			Lemoore NAS / Reeves Fld
		SID	
		LEM2EO	40
		REV5BU	40
KNQX			Key West NAS (Boca Chica Fld)
		SID	
		NQX6	40
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
		T32RZ	19
KTCM			Tacoma/McChord Fld /Joint Bas
		STAR	
		WHYTE7	40
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02	19
		T12	19
		T20	19
		T30	19
KWAL			Wallops Island/Wallops Flight
		APCH	
		T10	41
KWRB			Warner Robins/Robins AFB
		APCH	
		T15-Y	19
		T15-Z	19
		T33-Y	19
		T33-Z	19
LJCE			Cerklje ob Krki
		APCH	
		N08	22
MMAN			Monterrey/Del Norte Intl
		APCH	
		V20-W	11

*See Reason Code table on page R1

	Type	Procedure	Reason*
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
PAAD			Deadhorse/Point Thomson Aistr
		APCH	
		R05	40
		R23	40
PABP			Deadhorse/Badami
		APCH	
		R04	40
		R22	40
PACZ			Cape Romanzof LRRS
		APCH	
		R02	40
PADG			Red Dog
		APCH	
		R03	40
		R03-P	40
		SID	
		SICOV1	40
PADK			Adak Island/Adak
		APCH	
		R23-N	40
PADQ			Kodiak
		APCH	
		I26-Z	40
		L26-Z	40

*See Reason Code table on page R1

Type	Procedure	Reason*
PADU	Unalaska	
	APCH	
	N13	40
	N31	40
	R13	40
	R13-M	40
	R31	40
	R31-M	40
	SID	
	DUT1	40
PAGB	Galbraith Lake	
	APCH	
	R14	40
	SID	
	ARTIC2	40
PAIM	Utopia Creek/Indian Mountain L	
	APCH	
	N25	40
	R25	40
	SID	
	CLYDD4	40
PAJN	Juneau Intl	
	APCH	
	R08-T	40
PAKU	Kuparuk/Ugnu-Kuparuk	
	APCH	
	I06	40
	I24	40
	L06	40
	L24	40
	R06	40
	R24	40
PAKW	Klawock	
	APCH	
	R02-Z	40
PALP	Nuiqsut/Alpine Airstrip	
	APCH	
	R04	40
	R22	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
	SID		
		NUQST1	40
PALU			Cape Lisburne LRRS
	APCH		
		R27	40
	SID		
		GRAAY4	40
		LUR8	40
PAPG			Petersburg James A Johnson
	APCH		
		R23-P	40
PAPR			Prospect Creek
	APCH		
		R01-M	40
		R01-Z	40
		R19	40
	SID		
		CYCLE1	40
PASV			Sparrevohn LRRS
	APCH		
		N35	40
		R35	40
PATC			Tin City LRRS
	APCH		
		Q35	40
		R35	40
	SID		
		HONPO3	40
		JEKLI3	40
		TNC5	40
PATL			Takotna/Tatalina LRRS
	APCH		
		R35	40
	SID		
		TLJ4	40
PAVD			Valdez Pioneer Fld
	SID		
		FJORD1	40
		JOH2	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
RJBB			Kansai Intl
		STAR	
		CD01	42
		CD02F	42
		CD020	42
		CD03	42
		CD04	42
RJFA			Ashiya
		APCH	
		T12	19
RKSM			Seoul Domestic
		APCH	
		I20	22
		I20-Z	22
		L19	22
		L19-Z	22
		L20	22
		L20-Z	22
RKSO			Songtan-Si/Osan AB
		APCH	
		T09LZ	19
		T09RZ	19
		T27LZ	19
		T27RZ	19
TX25			Athens/Lochridge Ranch
		APCH	
		N17	40
UNSS			Strezhevoy
		SID	
		BUNA1Z	22
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final
42	Profile descent STARs

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55