

Navigation Database Addendum

AIRAC 2407 – Issue 17

AIP SB MAP effective 2nd December 2021

SBTV Terravista

APCH RNP RWY 15

APCH transition TV006 is missing from database.

Routing should read TV006 (IAF) - TV004 (IF).

Navdata will be updated effective AIRAC cycle 2408.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 11th July 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com