

## **Navigation Database Addendum**

AIRAC 2408 – Issue 13
NOTAM UE A3511/24 effective 9th June 2024

## **UEEE Yakutsk**

## All APCHs for RWY 05, Runway 05/23

Until 30SEP24 2359EST, RWY 05 landing threshold is displaced by 200 meters towards ARP.

- Vertical guidance should not be used, coded APCHs for RWY 05 do not lead to the displaced landing threshold.
- Declared distances should read RWY 05 TORA 3400 m TODA 3840 m ASDA 3400 m LDA 3400 m RWY 23 TORA 3400 m TODA 3850 m ASDA 3400 m LDA 3400 m

## Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 7<sup>th</sup> August 2024

All valid FSAs/NDAs are available on <a href="http://fms-info.lhsystems.com">http://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>