

## **Navigation Database Addendum**

## AIRAC 2410 – correction to Issue 2

NOTAM UE C4354/24 effective 29th August 2024

## **UERP Poliarny**

## All APCHs for RWY 18, Runway 18/36

Until 31MAR25 2359, RWY 18 landing threshold should read displaced by 600 meters towards ARP.

- RWY 18/36 operational length should read 2500 meters.
- Vertical guidance should not be used, all coded approaches do not lead to the displaced RWY 18 landing threshold.
- Declared distances should read RWY 18 TORA ASDA LDA 2500 meters TODA 2650 meters RWY 36 TORA ASDA LDA 2500 meters TODA 2650 meters.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Friday, 30<sup>th</sup> August 2024

All valid FSAs/NDAs are available on <a href="http://fms-info.lhsystems.com">http://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>