

Navigation Database Addendum

AIRAC 2505 – Issue 6

SUP LI S36/25 effective 15th May 2025

LIBP Pescara

Runway 04/22

From 15 May 2025 runway extension works will take place.
Works are divided into four phases that will be activated by Notam.

Phases 1, 2, 3:

- RWY length 2046 (m)
- Coordinates THR RWY 04 N42 25 26.61 E014 10 31.85
- THR Elevation RWY 04 45.5ft
- Aerodrome Elevation 45ft
- ILS not available
- Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW04	2046	2046	2046	2046
	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW22	2046	2106	2046	1858
Intersection take off B	1057	1117	1057	not available

Phase 4:

- ILS/DME RWY 22 operating with new ident IPSC
- New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 12th May 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com