



Navigation Database Addendum

AIRAC 2507 – Issue 12 Cancelled

AIRAC AMDT RP 001/25 effective 10th July 2025

NOTAMs RP B3261/25, C0762/25 and C0763/25

RPMY Cagayan de Oro Laguindingan Airport

Waypoints MAURI / NADUM / SIKIN

Following waypoint idents are not up-to-date in the NavDB:

- MORSO shall read MAURI in:
 - o SIDs MAURI 5A / MAURI 7A.
 - o STARs MAURI 2C / MAURI 4A / MAURI 6A.
- NUMBI shall read NADUM in:
 - o SIDs NADUM 5A / NADUM 7A.
 - o STARs NADUM 2C / NADUM 4A / NADUM 6A.
- SAKIB shall read SIKIN in:
 - o SIDs SIKIN 5A / SIKIN 7A.
 - o STARs SIKIN 2C / SIKIN 4A / SIKIN 6A.

Waypoint coordinates remain the same.

Navdata will be updated effective AIRAC cycle 2508.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 17th July 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com