

Navigation Database Addendum

AIRAC 2507 – Issue 13 SUP 04/2024 effective 25th January 2024

FZIC Kisangani Bangoka Intl

Runway 12

RWY 12 temporarily displaced by 750m.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 9th July 2025

All valid FSAs/NDAs are available on http://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com