

Navigation Database Addendum

AIRAC 2508 – Issue 13
NOTAM UC A0134/25 effective 31st July 2025

UCFM Bishkek / Manas

IATA code change

Late receipt of NOTAM -

• effective 9th August 2025, IATA code is changed from FRU to BSZ.

Navdata will be updated effective AIRAC cycle 2509.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Thursday, 7th August 2025

All valid FSAs/NDAs are available on http://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com