

Navigation Database Addendum

AIRAC 2508 – Issue 9

SUP LI S36/25 effective 15th May 2025

LIBP Pescara

Runway 04/22

From 15 May 2025 runway extension works will take place.
Works are divided into four phases that will be activated by Notam.

Phases 1, 2, 3:

- RWY length 2046 (m)
- Coordinates THR RWY 04 N42 25 26.61/ E014 10 31.85
- THR Elevation RWY 04 45.5ft
- Aerodrome Elevation 45ft
- ILS not available
- Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW04	2046	2046	2046	2046
	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW22	2046	2106	2046	1858
Intersection take off B	1057	1117	1057	not available

Phase 4:

ILS/DME RWY 22 operating with new ident IPSC
New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 5th August 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com