

Navigation Database Addendum

AIRAC 2509 – Issue 4

SUP 04/2024 effective 25th January 2024

FZIC Kisangani Bangoka Intl

Runway 12

RWY 12 temporarily displaced by **750m**.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 21st August 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com