



Navigation Database Addendum

AIRAC 2509 – Issue 5

SUP 164/25 effective 7th August 2025

ESGG Goteborg Landvetter

Runway 03/21

During the period 31 AUG – 16 SEP 2025, maintenance work will take place and the RWY will be shortened, available length 2200 m.

Following limitations are not included in the database:

RWY 03

- THR displaced by 1099 m.
- LDA 2200 m.
- TEMPO displaced THR coordinates: **N 57-39-30.17 E 012-16-32.75**

RWY 21

- From runway beginning:
TORA, TODA, ASDA and LDA 2200 m.
- From intersection TWY F:
TORA, TODA and ASDA: 2025 m.
- From intersection TWY E:
Not available.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 21st August 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com