



## Navigation Database Addendum

Monday, 27 October 2025

### AIRAC 2511 – Issue 8

LI SUP S36/25

### LIBP Pescara

---

From 15 May 2025 runway extension works will take place.  
Works are divided into four phases that will be activated by Notam.

#### Phases 1, 2, 3:

RWY length 2046 (m)

Coordinates THR RWY 04 N42 25 26.61/ E014 10 31.85

THR Elevation RWY 04 45.5ft

Aerodrome Elevation 45ft

ILS not available

Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

|                         | TORA (m) | TODA(m) | ASDA(m) | LDA (m)       |
|-------------------------|----------|---------|---------|---------------|
| RW04                    | 2046     | 2046    | 2046    | 2046          |
|                         | TORA (m) | TODA(m) | ASDA(m) | LDA (m)       |
| RW22                    | 2046     | 2106    | 2046    | 1858          |
| Intersection take off B | 1057     | 1117    | 1057    | not available |

#### Phase 4:

ILS/DME RWY 22 operating with new ident IPSC

New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)