

## **Navigation Database Addendum**

Thursday, 18 December 2025

## **AIRAC 2513 – Issue 4**

Source: SUP, Title: AIRAC SUP 102/A/25FC, Effective date: 27.11.2025

**NOTAM FC A1109/25** 

## **FPST Sao Tome Intl**

SID: RNP RWY 11/29 STAR: RNP RWY 29

**APCH: RNP RWY 29, VOR RWY 29** 

The implementation of the procedures published with AIRAC SUP 102/A/25FC effective 27-NOV-2025 has been postponed by NOTAM FC A1109/25 until 03-JAN-2026 EST. The following procedures in the database are suspended and should not be used:

RNP SIDs RWY 11/29 RNP STARs RWY 29 RNP APCH RWY 29 VOR APCH RWY 29

During this period, the following procedures are valid:

Conventional SIDs RWY 11/29 APCH VOR 29-T APCH NDB 29-T

(Suffix T is a Lido internal procedure name extension for procedure differentiation in the database and not used by ATC)

## Please disseminate this information to all affected crews.

Lufthansa Systems FMS Customer Support

All valid NDAs are available on <a href="https://fms-info.lhsystems.com">https://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>