



Navigation Database Addendum

Tuesday, 20 January 2026

AIRAC 2601 – Issue 10

Source: FZ SUP 04/2024, Effective date: 25 January 2024

FZIC Bangoka Intl

Runway: 12

RWY 12 temporarily displaced by **750m**.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com