



## Navigation Database Addendum

Thursday, 22 January 2026

### AIRAC 2601 – Correction to Issue 12

**Source: AIRAC SUP 102/A/25FC, Effective date: 27 November 2025**

**Source: NOTAM FC A0052/26, Effective date: 21 January 2026**

#### FPST Sao Tome Intl

---

**SID: RNP RWY 11/29**

**STAR: RNP RWY 29**

**APCH: RNP RWY 29, VOR RWY 29**

The implementation of the procedures published with AIRAC SUP 102/A/25FC effective 27-NOV-2025 has been postponed by **NOTAM FC A0052/26 until 02-APR-2026 EST**. The following procedures in the database are suspended and should not be used:

- RNP SIDs RWY 11/29
- RNP STARs RWY 29
- RNP APCH RWY 29
- VOR APCH RWY 29

During this period, the following procedures are valid:

- Conventional SIDs RWY 11/29
- APCH VOR 29-T
- APCH NDB 29-T

(Suffix T is a Lido internal procedure name extension for procedure differentiation in the database and not used by ATC)

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)