



Lufthansa Systems

Navigation Database Addendum

Tuesday, 20 January 2026

AIRAC 2601 – Issue 9

Source: NOTAM A0030/26 & A0031/26, Effective date: 22 January 2026

RKSS Gimpo Intl

APCH: ILS or LOC RWY 32L/R

According to NOTAM A0030/26 & A0031/26, MISAP procedures of ILS or LOC RWY 32L & ILS or LOC RWY 32R should read:

After 500ft, climb on HDG 324 to KIP D5 **N37-37.0 E126-43.1** (N 37° 36' 59.7" E 126° 43' 04.6"). Continue climb to 4000ft. Turn left direct to CAVOI. Hold as published.

Navdata will be updated effective AIRAC cycle 2602.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com