

## Navigation Database Addendum

Friday, 12 June 2026

### **AIRAC 2606 – Issue 14**

**AIRAC AMDT 02/26 effective 11JUN26**

### **HECA Cairo Intl**

---

The following Radar Departures are missing in NavDB:

**RWY 05L** CAIRO 1A: Left turn - 330° to FL060, CAIRO 1B: Climb on RWY heading to FL060.

**RWY 23R** CAIRO 1F: Right turn within D4 CAI - 300° to FL060.

**RWY 05C** CAIRO 1A: Left turn - 330° to FL060, CAIRO 1B: Climb on RWY heading to FL060.

**RWY 23C** CAIRO 1E: Climb on RWY heading to FL060.

**RWY 05R** CAIRO 1A: Left turn - 330° to FL060, CAIRO 1B: Climb on RWY heading to FL060, CAIRO 1C: Right turn - 120° to FL060.

**RWY 23L** CAIRO 1D: Left turn - 180° to FL060.

Expect radar vectors after DEP.

Departure flight shall contact Cairo Director 119.050 MHz upon passing 1000ft or as instructed by ATC.

Navdata will be updated effective AIRAC cycle 2607.

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)