

Navigation Database Addendum

Wednesday, 03 June 2026

AIRAC 2606 – Issue 7

EY SUP 05/26

EYVI Vilnius Intl

ILS Z and RNP missed APCHs

Until 1st July 2026, due to validity of less than one AIRAC cycle, the following **TEMPO missed APCHs are not updated** in database.

- **ILS Z RWY 01 MISAP should read:** "climb on RWY track (014°) to 5000 FT - radar vectoring will be provided" . **ILS Z RWY 19, MISAP should read:** "climb on RWY track (194°) to 5000 FT - radar vectoring will be provided" .
- **RNP RWY 01 MISAP should read** "climb on RWY track (014°) to 5000 FT - radar vectoring will be provided" . **RNP RWY 19 MISAP should read** "climb on RWY track (194°) to 5000 FT - radar vectoring will be provided" .

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com