



Navigation Database Addendum

Wednesday, 05 August 2026

AIRAC 2608 – Issue 10

Source: SUP 32/26, Effective date: 11.06.2026

ENNA Banak

Runway: 16/34

Works at the runway ends will be carried out in two different RWY configurations and during the following period:

- RWY Configuration South: 25 MAY 2026 - 10 JUL 2026
- RWY Configuration North: 10 JUL 2026 - 12 AUG 2026

These configurations have the following thresholds:

- RWY Configuration South: TEMPO THR RWY 16 / Standard THR RWY 34
- RWY Configuration North: Standard THR RWY 16 / TEMPO THR RWY 34

The database during this period does **NOT** reflect the TEMPO RWY Configurations

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

RWY Configuration South:

- RWY length 1910m
- Coordinates TEMPO THR RWY 16 N70 04 22.43 E024 58 21.12
- THR Elevation RWY 16 16.3ft

	TORA (m)	TODA(m)	ASDA(m)	LDA(m)
RW16	1910	2114	1910	1850
RW34	1850	1850	1850	1760

RWY Configuration North:

- RWY length 2350m
- Coordinates TEMPO THR RWY 34 N70 03 38.85 E024 58 31.34
- THR Elevation RWY 34 24.6ft

	TORA (m)	TODA(m)	ASDA(m)	LDA(m)
RW16	2290	2290	2290	2199
RW34	2259	3388	2259	2199

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com