



Navigation Database Addendum

Wednesday, 29 July 2026

AIRAC 2608 – Issue 5

Source: SUP 30/26, Effective date: 06 August 2026

SKCC Camilo Daza

STAR: DIMIL 2F, LUCHA 2A, TIBUS 2F

APCH: RNP A RWY 21, RNP A RWY 34

STARs DIMIL 2F, LUCHA 2A, TIBUS 2F are missing for RWY 34.

RNP A RWY 21 and **RNP A RWY 34:**

MISAP should include an active holding leg at CUC:

INBD 006deg, LEFT, Max 190KT, 1 MIN.

Navdata will be updated effective AIRAC cycle 2609.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com