



Navigation Database Addendum

Monday, 31 August 2026

AIRAC 2609 – Issue 7

Source: NOTAMs A2845/26, A2864/26, A2883/26, A2896/26

Effective date: 03 September 2026

VVPQ Phu Quoc Intl

Runway: 10/28, All flight procedures

Due to late receipt of NOTAM A2896/26 which postpones the introduction of the new runway 10L/28R until 01 OCT 2026 at 0000 UTC, the only operational runway available until 30 SEP 2026 is RWY 10/28.

Consequently, all flight procedures coded in the database are unusable from 03 SEP 2026 at 0000 UTC until 30 SEP 2026 at 2359 UTC. Additionally, the following procedures are not included in the database from 03 SEP 2026 at 0000 UTC until 30 SEP 2026 at 2359 UTC:

SID	Runway	Procedure Name
	RNP RWY 10	HOTUN 1D MINTU 1A NORTI 1A NUMDI 1D OSOTA 1D
	RNP RWY 28	TRUMI 2A HOTUN 1C NUMDI 1C OSOTA 1C THILI 1C TATEM 2A

SID	Runway	Procedure Name
	RWY 10	OSOTA 1B NUMDI 1B TUNPO 1B ADBOP 1B
	RWY 28	OSOTA 1A NUMDI 1A TUNPO 1A ADBOP 1A

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

STAR	Runway	Procedure Name
	RNP RWY 10	TRUMI 2B HOTUN 1F NUMDI 1F OSOTA 1F THILI 1B TATEM 1B
	RNP RWY 28	HOTUN 1E MINTU 1B NUMDI 1E OSOTA 1E TIHAN 1C

STAR	Runway	Procedure Name
	RWY 10/28	OSOTA 1A NUMDI 1A TUNPO 1A ADBOP 1A
	RWY 28	TUNPO 1B ADBOP 1B

IAP	Procedure Name
	VOR RWY 10 VOR RWY 28 RNP Z RWY 10 RNP Y RWY 10 RNP X RWY 10 RNP Z RWY 28 RNP Y RWY 28 RNP X RWY 28

Furthermore:

- RWY 10R/28L in the database should read RWY 10/28.
- Landing distance available for RWY 10/28 should read 3000m.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com